#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patentee: Ford Global Technologies, LLC

Patent No.: 7,308,732 B2 Application No.: 10/536,661

Issued: December 18, 2007 Filed: November 27, 2003

Primary Examiner: Chuck Y. Mah

For: ADJUSTABLE HINGE ASSEMBLY

Attorney Docket No.: 81117315 (FGT 1986 PA/36190-808)

### REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450.

Sir:

Patentee hereby petitions under the provisions of 35 U.S.C. Section 254 for a Certificate of Correction to correct the errors set forth on the enclosed Certificate of Correction.

If said request is granted, Patentee requests the file be forwarded to Certificates of Correction Branch, for issuance of a Certificate of Correction.

The Commissioner is authorized to charge any fees to Deposit Account No. 06-1510 in the name of Ford Global Technologies, Inc.

Respectfully submitted,

**DICKINSON WRIGHT PLLC** 

/Jerome R. Drouillard/

Jerome R. Drouillard, Reg. No. 28,008 38525 Woodward Avenue, Suite 2000 Bloomfield Hills, MI 48304

Phone: (248) 433-7200

Fax: (248) 433-7274

Dated: March 5, 2008 BLOOMFIELD 36190-808 889712v1 Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

		Page 1 of 2
ATENT NO.	: 7,308,732 B2	——————————————————————————————————————

APPLICATION NO.: 10/536,661

ISSUE DATE : December 18, 2007

INVENTOR(S) : Timothy Woolcock

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### In The Specification:

Column 1, Line 63, should read as follows: -- which in use faces the other side of the flange, and a shank, --

Column 2, Line 57, should read as follows: -- position. The adjustment nut is then rotated to bring the first --

Column 3, Line 3, should read as follows: -- with reference to the accompanying drawings: --

Column 4, Line 4, should read as follows: -- The hollow flange 34 is formed by an upper pressing 51, --

Column 4, Line 58, should read as follows: -- brought into its correct position, with the spacer 58 having --

Column 4, Line 66, should read as follows: -- the thread 41 engages the friction ring 46. The thread 41 --

Column 5, Line 9, should read as follows: -- locking screw 26 will then continue to rotate without further --

Column 5, Line 35, should read as follows: -- the external thread 36 of the second hinge member 22 with the

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Jerome R. Drouillard 38525 Woodward Avenue, Suite 2000 Bloomfield Hills, MI 48304

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 2 of 2

PATENT NO. : 7,308,732 B2

APPLICATION NO.: 10/536,661

ISSUE DATE : December 18, 2007

INVENTOR(S) : Timothy Woolcock

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In The Specification:

Column 5, Line 50, should read as follows: -- 3 with the addition of 100. The adjustment nut 125 differs in that

Column 5, Line 51, should read as follows: -- there is no friction ring 46 and also that the bore of the --

Column 6, Line 7, should read as follows: -- nut 225 again differs in that there is no friction ring 46 --

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Jerome R. Drouillard 38525 Woodward Avenue, Suite 2000 Bloomfield Hills, MI 48304

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.